

DMV Lane Technician Observation Report

DMV Technician: <u>Rodriguez</u>		Position: <u>LP 2</u>	
Station: <u>Wilm</u>	Date: <u>6-24-14</u>	Time: <u>12:55</u>	
Vehicle Make: <u>Hyundai</u>	Model	Year	
GVWR:	Fuel Type: <u>GAS</u>	Registration Number: <u>791954</u>	
Auditor: <u>Coverdale</u>		<u>Covert</u> /Overt (Circle One)	
	YES	NO	N/A
1. Did technician check vehicle paper work and verify VIN number?	<u>✓</u>		
2. Was Emissions testing required?	<u>✓</u>		
a) Was Emissions testing performed using OBD?	<u>✓</u>		
b) Was Emissions testing performed using Analyzer Probe?			
c) Was Emissions testing performed using Paddle(s)?			
d) Was Emissions testing performed using Clip?			
3. Was Catalytic Converter inspection required?			<u>✓</u>
a) Was Catalytic Converter inspection performed?			
4. Was Fuel Tank pressure testing required?			<u>✓</u>
a) Was Fuel Tank pressure testing performed?			
5. Was Fuel Cap pressure testing required?			<u>✓</u>
a) Was Fuel Cap pressure testing performed?			
6. Is this test a Re-check from a prior failure?		<u>✓</u>	
a) Which re-check test is being performed? 1 2 3 (circle one)			
b) If this is re-check #3, was repair paperwork verified for waiver?			
Sussex County Only			
7. Was Curb Idle testing required?			
a) Was Curb Idle testing performed?			
Comment:			

Original 08/06/2009/TMP